



## EXTERNAL BUTTONS "TARA - PRINT"



Buttons for remote release of functions TARE and PRINT.  
Cable connection to the weighing instrument.  
Cable length 1,5m.  
Casing out of plastics.

Buttons are offered in below specified versions:  
-Pt0021 for PUE C41H indicator, PUE HY indicator  
-P0168 for terminal TMC



### Specification:

Mechanical durability	>1000000 weighing cycles
Operation frequency	<3600 cycles / hour
Cable length	1,5m standard
Working temperature	-25° ÷ +40°C
IP rating	IP 54
Dimensions	120 × 80 × 56